



NHRA Sportsman Q-Card Guidelines and Policies

NHRA Sportsman Q-Card is available to competitors in Super Stock, Stock Eliminator, Super Comp, Super Gas and Super Street. The program will expedite the tech and registration process onsite at each of the 24 NHRA National Events.

Requirement to Participate in NHRA Sportsman Q-Card:

1. Must be in good standing with NHRA.
2. Have a current Extended Tech Inspection (ETI) on file with the NHRA Tech Department.
 - a. ETI can be completed at a chassis seminar, national or divisional event either before the event has started or once eliminated from competition.
3. Have a current year sportsman hard card (\$100 processing fee for hard card).
 - a. **Link:** [How to apply for a Sportsman Hard Card](#)
4. Program limited to SS, STK, SC, SG and SST
5. Competitors may be required to bring their vehicle to inspection line for random screening.

On Site Procedure:

1. Competitor will need to print, complete and sign the online tech card located on www.NHRAEventReg.com.
 - a. **Link:** [How to access National Event Online Tech Card](#)
2. Completed and signed online tech card will be collected by an NHRA Pit Control Official upon being pulled into the facility.
 - a. Competitor will be required to present a copy of the Extended Tech Inspection (ETI) form at the **first** National Event attended using the NHRA Sportsman Q-Card process.
3. Report to the staging lanes when your category is called.